carbon powder and metal powder are formed or disposed on copper foil surfaces of 2 to 10 copper-clad laminates, one coating or sheet on the copper foil surface of one copper-clad laminate, the 2 to 10 copper-clad laminates are stacked, and the upper surface of the stacked copper-clad laminates is irradiated with the carbon dioxide gas laser to form the penetration holes at the same time.

IN THE CLAIMS:

Please cancel claims 1-10 without prejudice to the subject matter thereof.

BEST AVAILABLE